

VCDS-Lite
Windows Based VAG/VAS Emulator
Version: Release 1.2
www.Ross-Tech.com

Workshop Code: 000 00000

Self-Diagnosis Log
Friday, 16 August 2013, 12:35:31.

VIN Number: License Plate:
Mileage: Repair Order:

Chassis Type: 3BG - myPassat TDI
Scan: 01,03,08,15,17,19,46

Address 01: Engine Labels: 038-906-019-AVF.LBL
 Controller: 038 906 019 KD
 Component: 1,9l R4 EDC G400SG 4897
 Coding: 00002
 Shop #: WSC 05314
 VCID: 63B92C8FE24D
 WVWZZZ3BZ5E010865 VWZ7Z0D9808678
No fault code found.
Readiness: N/A

Address 03: ABS Brakes Labels: 4B0-614-517.LBL
 Controller: 4B0 614 517 G
 Component: ABS/ESP front 3428
 Coding: 04255
 Shop #: WSC 05311
 VCID: 253D7297ACF9
No fault code found.

Address 08: Auto HVAC Labels: 3Bx-907-044.LBL
 Controller: 3B1 907 044 K
 Component: CLIMATRONIC B5GP 0010
 Coding: 17000
 Shop #: WSC 05311
 VCID: 29257EA7C0E1
No fault code found.