

VCDS-Lite
Windows Based VAG/VAS Emulator
Version: Release 1.2
www.Ross-Tech.com

Workshop Code: 000 00000

Diagnostic Trouble Code Report
Saturday, 21 May 2022, 16:34:43:36321

VIN Number: WVWZZZ3BZ4E120450 License Plate: SHA-NM-221
Mileage: 306552 Repair Order: 200456-22

Control Module Part Number: 038 906 019 KD
Component and/or Version: 1,9l R4 EDC G000SG 4897
Software Coding: 00002
Additional Info: WVWZZZ3BZ4E120450 VWZ7Z0C8210540

1 Fault Found:

16485 - Mass Air Flow Sensor (G70): Implausible Signal
P0101 - 35-10 - - - Intermittent

Readiness: N/A