

04/1995, 20000 km ADAC Prüfdienst, SUN MAC 4			
	links		rechts
Vorderachse			
Sturz	-1°09'		-0°55'
Einzelspur	-0°40'		-0°37'
Gesamtspur		-0°04'	
Nachlauf	+2°07'		+2°44'
Spreizung	+13°02'		+12°07'
Spreizung+ Sturz	+11°54'		+11°12'

06/1997, 60960 km VAG 1813			
	links		rechts
Hinterachse			
Sturz	-1°43'		-1°43'
Spur	+0°08'		+0°17'
Gesamtspur		0°25'	
Vorderachse			
Sturz	-1°03'		-0°57'
Spur	+0°12'		+0°06'
Gesamtspur		0°18'	

05/2002, km 161000 ADAC Prüfdienst, SUN MAC 4			
	links		rechts
Vorderachse			
Sturz	-1°03'		-0°47'
Einzelspur	+0°10'		+0°08'
Gesamtspur		+0°18'	
Nachlauf	+2°16'		+2°53'
Spreizung	+13°22'		+15°32'
Spreizung + Sturz	+12°19'		+14°44'

12/2004, km 222500 ADAC Prüfdienst, SUN MAC 4			
	links		rechts
Hinterachse			
Sturz	-1°30'		-1°32'
Einzelspur	-0°10'		+0°05'
Gesamtspur		-0°05'	
Geometrische Fahrachse		-0°08'	
Vorderachse			
Sturz	-0°45'		-0°55'
Einzelspur	+0°04'		+0°04'
Gesamtspur		+0°06'	
Nachlauf	+2°24'		+2°48'
Spreizung	+12°53'		+4°30'
Spreizung + Sturz	+12°09'		+3°35' +3°53'
Radversatz		-0°11'	